



The achieved flexibility is maintained



1. Linearity of the graph almost to the top - indicates that the material is stable and withstood cracking.
2. After the peak (ie the graph after the peak) indicates that the material is durable and flexible. This means that we do not see brittle cracking under heavy loads, which is also proof of good elasticity.